

Oil Field Environmental Incident Summary

Incident: 20151026122004 **Date/Time of Notice:** 10/26/2015 12:20
Responsible Party: ENERPLUS RESOURCES USA CORPORATION
Well Operator: ENERPLUS RESOURCES USA CORPORATION
Well Name: CACTUS CTB
Field Name: HEART BUTTE **Well File #:**
Date Incident: 10/26/2015 **Time Incident:** 10:00 **Facility ID Number:** 229788-01
County: DUNN **Twp:** 149 **Rng:** 92 **Sec:** 35 **Qtr:** NE NW
Location Description:

Submitted By: Shannon Oliver **Received By:**
Contact Person: Josh Ruffo
US BANK TOWER
950 17TH ST STE 2200
DENVER, CO 80202

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Facility Site **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

Risk was low and fire was put out by Enerplus personnel.

Areal Extent:

Fire was contained to the area around the base of the flare and along the perimeter containment.

Potential Environmental Impacts:

Minimal environmental impact as entire incident was maintained on location.

Action Taken or Planned:

Shut in wells and drained knockout vessels. Put out fire with hand-held fire extinguisher and dirt. Wells are shut-in until cause can be determined and make appropriate repairs.

Wastes Disposal Location: No wastes were recovered, all spilled material burned.

Agencies Involved:**Updates**

Date: 10/27/2015 **Status:** No Further Action Requested

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Fire remained within well pad perimeter. No further action required at this time.